



**GLOBAL TECHNIK CORP®**

# FLEETS

Repair and Overhaul



## HEILICOPTERS

Bell, Boeing, CH, Robinson, McDonnell, Douglas, Sikorsky,  
Agusta, Eurocopter, HH65, Airbus

**Specializing in commercial, commuter and military aircrafts**

Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)




**GLOBAL TECHNIK CORP<sup>®</sup>**

# HARNESSES

## Repair and Overhaul

Global Technik has repair and overhaul capabilities on Harness. Our highly trained and skilled technicians operate with maximum efficiency and precision - thus extending the life and increasing the reliability of these components.

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# AIR CYCLE MACHINES

Repair and Overhaul

**EMBRAER**  
**PART NUMBER**  
2204540-2  
2204540-4  
815240-1  
815240-2  
815240-3

**CRJ200/700/900**  
**PART NUMBER**  
7827090-15  
GG670-95009-1  
GG670-95009-3  
GG670-95009-5  
GG670-95009-7

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# STARTERS AND GENERATORS

Repair and Overhaul

**EMBRAER**  
**EMB-170/175/190/195**  
PART NUMBER  
4120T06P04

**CRJ200/700/900**  
PART NUMBER  
3505188-9 | 3505953-2  
3505953-4 | 3505953-6  
3505953-2 | 3505953-4  
3505953-6

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP.**

# HYDRAULIC PUMP

Repair and Overhaul

**PART NUMBER**

887055  
3032467-001  
601R75113-3  
601R75113-5

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# VALVE MODULATING


Repair and Overhaul

**PART NUMBER**

3214442-3

3214442-4

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# COWL DE-ICE VALVE

Repair and Overhaul


**PART NUMBER**

300013000-003

5399-00-5

5399-00-3

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# STANDBY INDICATOR

Repair and Overhaul

**PART NUMBER**

C16221AA02

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)





**GLOBAL TECHNIK CORP®**

# SHUT OFF VALVE


Repair and Overhaul

## PART NUMBER

242114-3	L92B19-602
242113-2	L92C13-602
242114-1	L92B13-605

**NO MORE EVALUATION FEE**

Current Turn Around Time 7 days



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# AIR CYCLE MACHINE

Repair and Overhaul

EMB-170 | EMB-175  
EMB-190 | EMB-195

**PART NUMBER**

1000700-3  
1000700-4  
1000700-5  
1000700-6  
1000700-7  
4120T06P04

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP.**

# WATER HEATER

Repair and Overhaul

**PART NUMBER**

24E507009G01

24E507009G02

24E507009G03

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP.**

# B/E COFFEE MAKER

Repair and Overhaul

**PART NUMBER**


3510-0039-01

3510-0044-05

3510-0066-01

416-0001-23

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# EMERGENCY LOCATOR

Repair and Overhaul

PART NUMBER	
S1818502-02	S1822502-02
S1819502-02	S1823502-01
S1820502-01	S1823502-02
S1820502-02	S1823502-03
S1821502-01	S1823502-05
S1821502-02	S1824502-01
S1822502-01	S1824502-02
	S1826502-01

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP.**

# HANDWHEEL TRANSMITTER

Repair and Overhaul

**PART NUMBER**

322200-1M00

322200-2M00

322200-7M00

322200-8M00

322200-9M00

322200- 10M00

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# PITOT TUBE

Repair and Overhaul

**PART NUMBER**

0851HL  
0851HT-1  
0851HU  
0851JW1  
0851MC

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP.**

# OXYGEN BOTTLES

Repair and Overhaul

**PART NUMBER**

3552AAADAACXCD

9700-C1A-F23AN

9700-C1A-BF23A

891511-14

89794015

## NO MORE EVALUATION FEE

Global Technik has repair and overhaul capabilities on Oxygen Bottles.

Our highly trained and skilled technicians operate with maximum efficiency and precision, thus extending the life and increasing the reliability of these components.



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)





**GLOBAL TECHNIK CORP<sup>®</sup>**

# B/E WATER BOILER

Repair and Overhaul

**PART NUMBER**  
4360004-85-00-18

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# BRAKE MONITORING UNIT

Repair and Overhaul

**PART NUMBER**  
35-1H5-00-1002  
LA2H60300HM0100

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# COVER ASSEMBLY

Repair and Overhaul

**PART NUMBER**

145-65129-407

145-65129-408

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# CONSTANT SPEED MOTOR

Repair and Overhaul

**PART NUMBER**  
520913

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)




**GLOBAL TECHNIK CORP®**

# **ELECTRIC PUMP HYDRAULIC**

Repair and Overhaul

**PART NUMBER**  
693335

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# EVT FAN

Repair and Overhaul

## PART NUMBER

EVT174-2E1	EVT174-2E41	EVT174-2E8	EVT3454D
EVT174-2E2	EVT174-2E5	EVT174-2E9	EVT3454F
EVT174-2E3	EVT174-2E51	EVT3454A	EVT3454G
EVT174-2E31	EVT174-2E6	EVT3454B	EVT3454H
EVT174-2E4	EVT174-2E7	EVT3454C	EVT3454HC
			EVT3454J

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP.**

# ACTUATORS

Repair and Overhaul

FILL / DRAIN VLV ACTUATORS  
D05-SERIES

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# INTEGRATED DRIVE GENERATOR

Repair and Overhaul

**PART NUMBER**  
740119H-1

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)





**GLOBAL TECHNIK CORP<sup>®</sup>**

# B/E OVENS

Repair and Overhaul

**PART NUMBER**

PN: 720730-00-43-00

PN: 4323100-00-66-22

PN: 72067000 / 72067002 / 72073000

SELL OVEN

PN: 8203-11-0000

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# AIR COOLING TURBINE

Repair and Overhaul

**ATR-42 / 72**  
PART NUMBER  
2204400-x  
2205120-x

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# PNEUMATIC VALVE

Repair and Overhaul

**PART NUMBER**

3214560-2

3214960-2

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# HYDRAULIC COMPONENTS

Repair and Overhaul

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# WL-STBY ALTIMETER INDICATORS

Repair and Overhaul

**PART NUMBER**

WL102AMS3

WL101AMS5

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# PUMP HYDRAULIC

ELECTRIC MOTOR  
Repair and Overhaul

**PART NUMBER**

51154-04

PN: 51154-05

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# STROBE LIGHTS

Repair and Overhaul

## TAIL STROBE LIGHT

2LA005303-05  
2LA005308-05

## WARNING RED LIGHT

2LA005467-00

## LOGO LIGHTS

2LA456342-01  
2LA456342-02  
2LA456342-03  
2LA456342-04

## STROBE LIGHT

2LA456241-00

## LIGHT ASSY TAIL LIGHT

2LA006181-01

## PANEL WARNING LIGHT

2LA007307-00

## EMERGENCY LIGHTS

2LA005127-00  
2LA005128-00  
2LA005127-01  
2LA005128-01  
2LA005127-10  
2LA005128-10  
2LA005127-20  
2LA005128-20  
2LA005127-30  
2LA005128-30

2LA005413-00  
2LA005414-00  
2LA005413-01  
2LA005414-01  
2LA005413-10  
2LA005414-10  
2LA005413-20  
2LA005414-20  
2LA005413-30  
2LA005414-30

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# LANDING LIGHTS

Repair and Overhaul

## PART NUMBER

45-0083-7	45-0057-9	4315542
45-0013-3	45-0234-3	G-6250-4
45-0068-7	45-0212-1	G8385-1
45-0093-1	44040-4557	G5400-5
45-0263-11	44040	145-11452-601
45-0263-22	50-0137-3	10-3294-4
45-0263-5011	50-0014-9	G3600A1
45-0351-6	50-0015-8	G5400-15
45-0351-5	50-0326-3	G5400-1
45-0351-3		

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)





**GLOBAL TECHNIK CORP®**

# DIRECTIONAL GYRO

Repair and Overhaul

**ROLL STAB DIR GYRO**

17221-2A  
17221-2B

**DIR. DISPL. GYRO**

17265-1A  
17265-2A

**RATE GYRO**

1782137-2  
1782137-3

**VERT GYRO**

1782356-11  
1782356-111

**ELEC GYRO ATT IND**

17502-1D-A1  
17502-1D-B1  
17502-1D-C2

**DIRECTIONAL GYRO**

17237-1A  
17237-3A  
17237-5A

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# SURVIVAL KITS

Repair and Overhaul

**PART NUMBER**

60128-101

60128-103

60128-301

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP<sup>®</sup>**

# FLAP TRANSMISSION BRAKE

Repair and Overhaul

**PART NUMBER**

363500-1003

**NO MORE EVALUATION FEE**



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# FIRE EXTINGUISHER

Repair and Overhaul

## What Types of Aircraft Fire Extinguishers Do We Service?

We inspect, repair and overhaul several different types of aviation fire extinguishers:

- Halon 1211 portables:** This agent is used in handheld portable extinguishers and extinguishes in-cabin fires.
- Halon 1301 engine, APU and cargo systems:** 1301 is used in fixed fire extinguishers installed throughout the plane which flood the specific areas, removing the oxygen, extinguishing the fire.
- H2O portables:** These fire extinguishers use water and pressurized air to extinguish fires in the cabin and galley.
- CO2 systems:** Handheld and fixed fire extinguishers utilizing liquid CO2, typically used on older aircraft.

## What Brands and Manufacturers Do We Service?

Our aerospace fire extinguishing services allow customers to maintain and repair their aircraft systems. Our skilled technicians have the knowledge, experience and resources to service extinguishers from numerous major brands and manufacturers, including:

Pac Sci/HTL  
Meggitt  
Kidde/Walter Kidde/Kidde Dexaero/Graviner  
Mass Systems  
L'Hotellier



Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)



**GLOBAL TECHNIK CORP®**

# WHEELS

Repair and Overhaul



**BOMBARDIER**  
Gulfstream

**AIRBUS**  
*Q* **BOEING**

Headquarters: 325 m Sur del Rancho Cámara de Cañeros, La Ceniza, Pérez Zeledón, San José, Costa Rica  
Logistic Center: 2910 Belmeade-Suite #108 Carrollton, Texas 75006  
FAA Repair Station FJ4R628X - EASA. 145.5535  
[www.global-technik.com](http://www.global-technik.com)